

Made Daw	14 CC 2 C			7
Work Perm	it# <u>SS-2</u> 0	05-060	3/- 0	000
Work Orde	r#		0)	
Job#	Activity#	1. 16 2		100

Vork requester fills out this section.		Work Permit		·····9" —	
Requester: Don Lynch	Date: 06/06/05	Ext.: 2253	Dept/Div/Group: PO/I	PHENIX	
Other Contact person (if different from	requester): S. Marino		Ext.: 3704		
rk Control Coordinator: Don Lynch nef Description of Work:	nain Carle	Start Date: 06/07/05	Est. End Date: 06/25/	/05	
Building: 1008	Room: IR	Equipment n/a	トルウC・ Service Provider: PHI	EKIIV	
C, Requester/Designee, Service Provi		out this section or attach ana	lysis	EINIA.	
ES&H ANALYSIS	Charles the Control of the Street				
	None	Airbome	Contamination	Radiation	
Radiation Generating Devices: Special nuclear materials involved		Moisture Density Gauges	Soil Density Gauges	X-ray Equipment	
Safety Concerns	None None	☐ Ergonomics	☐ Transport of Haz/Rad Ma	olved, notify Laboratory Criticality Officer	
☐ Adding/Removing Walls or Roofs	Confined Space*	Explosives	Lead*	Penetrating Fire Walls	
Adding/Aemoving Walls of Roots	Corrosive	☐ Flammable	☐ Magnetic Field*	☐ Pressurized Systems	
Asbestos*	Cryogenic	☐ Fumes/Mist/Dust*	☐ Material Handling	☐ Rigging/Critical Lift	
Beryllium*	☐ Electrical	Heat/Cold Stress	☐ Noise*	☐ Toxic Materials*	
Biohazard* Chemicals*	☐ Elevated Work*	Hydraulic	☐ Non-ionizing Radiation*	☐ Vacuum	
* Does this work require medical clean		tional Medicine Clinica CT V	Oxygen Deficiency*	Other	
Environmental Concerns	ande of surveillance from the Occupa	None None	■ Work impacts Environme	ntal Permit No	
☐ Atmospheric Discharges (rad/non-	-rad)	☐ Land Use	Soil	The second secon	
<u> </u>			Activation/contamination	☐ Waste-Mixed	
☐ Chemical or Rad Material Storage	oruse	☐ Liquid Discharges ☐ Oil/PCB	☐ Waste-Clean	☐ Waste-Radioactive	
Cesspools (UIC)		Management	☐ Waste-Hazardous	☐ Waste-Regulated Medical	
☐ High water/power consumption		Spill potential	☐ Waste-Industrial	Underground Duct/Piping	
Waste disposition by:				Other	
Pollution Prevention (P2)/Waste Min	Imization Opportunity:	☑ None ☐ Yes		No.	
	☐ Electrical Noise	Potential to Cause a F	alse Alarm	Vibrations	
☐ Access/Egress Limitations	☐ Impacts Facility Use Agre	and the second s	☐ Temperature Change	Other	
7 Configuration Control	☐ Maintenance Work on Ver	Control of the Contro	Utility Interruptions	1000	
ORK CONTROLS	Marita Tarana MA	CARE DEADLY AND		A SMOOTH ASSESSMENTS	
Work Practices				Tank Bridge McConstitution	
None	Exhaust Ventilation	☐ Lockout/Tagout	Spill Containment	☐ Security (see Instruction Sheet)	
Back-up Person/Watch Back-up Pers	☐ HP Coverage	Posting/Warning Signs	☐ Time Limitation	Other	
☐ Barricades	☐ IH Survey	Scaffolding-requires	☐ Warning Alarm (i.e. *high I	evel")	
	D 11.0015)	inspection	Warning Alamir (i.e. h)gjiri	CVGIT	
Protective Equipment.	☐ Ear Plugs	Gloves	Lab Coat	☐ Safety Glasses	
☐ Coveralls	☐ Ear Muffs	Goggles	Respirator	Safety Harness	
☐ Disposable Clothing	☐ Face Shield	☐ Hard Hat	☐ Shoe Covers	IXI Safety	
		E naiu nai	Silve covers	Shoes Other	
Permits Required (Permits must be va	Cutting/Welding	Impair Fire Destaction	<u>Madelini (2006)</u> Sustano	umad uesul statistissis (2	
☐ Concrete/Masonry Penetration	Digging/Core Drilling	Impair Fire Protection Rad Work Permit-RWF			
Confined Space Entry	☐ Electrical Working Hot	Other	100		
Dosimetry/Monitoring					
None ∴	☐ Heat Stress Monitor	Real Time Monitor	☐ TLD		
☐ Air Effluent	☐ Noise Survey/Dosimeter	Self-reading Pencil Dosimeter	☐ Waste Characterization		
	ET O MOSSINGER OSS	Self-reading Digital			
☐ Ground Water	☐ O ₂ /Combustible Gas	Dosimeter	☐ Other		
Liquid Effluent	☐ Passive Vapor Monitor	Sorbent Tube/Filter			
Fraining Requirements (List below spe		Pump	A 1/2 / 1/2		
PHENIX Awareness, LockOut/TagOut a		nhts			
Based on analysis above the Walkdo	ACTION CALL DOWN TO A TANK THE STANK WILL	BOTTON CONTROL OF THE	If using the permit when all h	azard ratings are low, only the following	
Based on analysis above, the Walkdo ratings below:	wil realitueterinines the risk, com	prestry, and coordination		ved, there is no need to use back of	
The state of the s	☐ Low ☐ Moderate	☐ High	form) WCC:	Date:	
AH Risk Level.	☐ Low ☐ Moderate	High	Service Provider.	Date:	
Work Coordination:	☐ Low ☐ Moderate	☐ High	Authorization to start	Dafe:	
AND CONTRACTOR AND PROPERTY.	A L Low A moderate		(Departmental Sup/WCC/Design		



Work	Permit #	
Work	Order #	
Job#	Activity#	

Nork requester fills out this section.	☐ Standing	Work Permit		, <u> </u>
Requester: Don Lynch	Date: 06/06/05	Ext.: 2253	Dept/Div/Group: PO/F	PHENIX
Other Contact person (if different from r	equester): S. Marino		Ext.: 3704	
Work Control Coordinator: Don Lynch		Start Date: 06/07/05	Est. End Date: 06/25/	/05
Brief Description of Work:				
Building: 1008	Room: IR	Equipment: n/a	Service Provider: PHE	ENIX
CC, Requester/Designee, Service Provi	der, and ES&H (as necessary) fill o	out this section or attach anal	ysis	
ES&H ANALYSIS	<u> </u>			
	None	Airborne	☐ Contamination	Radiation
	•	Moisture Density Gauges	Soil Density Gauges	X-ray Equipment
☐ Special nuclear materials involved	d, notify Isotope Special Materials Gr	oup	☐ Fissionable materials inv	olved, notify Laboratory Criticality Officer
Safety Concerns	None	☐ Ergonomics	☐ Transport of Haz/Rad Ma	aterial _
☐ Adding/Removing Walls or Roofs	☐ Confined Space*	☐ Explosives	☐ Lead*	☐ Penetrating Fire Walls
	Corrosive	☐ Flammable	☐ Magnetic Field*	☐ Pressurized Systems
☐ Asbestos*	Cryogenic	☐ Fumes/Mist/Dust*		☐ Rigging/Critical Lift
☐ Beryllium*	☐ Electrical	☐ Heat/Cold Stress	☐ Noise*	☐ Toxic Materials*
☐ Biohazard*		☐ Hydraulic	☐ Non-ionizing Radiation*	☐ Vacuum
☐ Chemicals*	☐ Excavation	☐ Lasers*	☐ Oxygen Deficiency*	☐ Other
* Does this work require medical clear	ance or surveillance from the Occup	ational Medicine Clinic? TY	es 🔀 No	
Environmental Concerns		None Non	☐ Work impacts Environme	ental Permit No.
☐ Atmospheric Discharges (rad/non	ı-rad)	☐ Land Use	Soil Activation/contamination	☐ Waste-Mixed
☐ Chemical or Rad Material Storage	o or Uso	☐ Liquid Discharges	Activation/contamination Maste-Clean	☐ Waste-Radioactive
	s or ose	☐ Cil/PCB	 	
Cesspools (UIC)		Management	☐ Waste-Hazardous	☐ Waste-Regulated Medical
☐ High water/power consumption		☐ Spill potential	☐ Waste-Industrial	☐ Underground Duct/Piping
Waste disposition by:			☐ Other	
Pollution Prevention (P2)/Waste Min	nimization Opportunity:	None Yes		
FACILITY CONCERNS	None Non			
Access/Farence Limitations	☐ Electrical Noise	☐ Potential to Cause a I	False Alarm	☐ Vibrations
Access/Egress Limitations	☐ Impacts Facility Use Agr	reement	☐ Temperature Change	☐ Other
☐ Configuration Control	☐ Maintenance Work on V	entilation Systems	☐ Utility Interruptions	•
WORK CONTROLS				
Work Practices				
None	☐ Exhaust Ventilation		☐ Spill Containment	☐ Security (see Instruction Sheet)
☑ Back-up Person/Watch	☐ HP Coverage	☐ Posting/Warning Signs	☐ Time Limitation	☐ Other
Barricades	☐ IH Survey	Scaffolding-requires inspection	☐ Warning Alarm (i.e. "high	n level")
Protective Equipment				
None	☐ Ear Plugs	Gloves	☐ Lab Coat	☐ Safety Glasses
☐ Coveralls	☐ Ear Muffs	Goggles	Respirator	Safety Harness
☐ Disposable Clothing	☐ Face Shield	☐ Hard Hat	☐ Shoe Covers	Safety Other
_ '	ralid when ich is sehedulad \		1	Shoes
Permits Required (Permits must be v		Impair Fire Dratection	Cuatama	
Concrete/Masonry Penetration	☐ Cutting/Welding ☐ Digging/Core Drilling	☐ Impair Fire Protection☐ Rad Work Permit-RW		
Confined Space Entry	☐ Electrical Working Hot	Other	P NO	
	Li Electrical Working Hot	☐ Other		
Dosimetry/Monitoring	☐ Heat Stress Monitor	Dool Time Meniter	T TID	
None		Real Time Monitor Self-reading Pencil	☐ TLD	
☐ Air Effluent	Noise Survey/Dosimeter	Dosimeter Self-reading Digital	☐ Waste Characterization	
Ground Water	O ₂ /Combustible Gas	Dosimeter Sorbent Tube/Filter	Other	
Liquid Effluent	Passive Vapor Monitor	Pump		
Training Requirements (List below s				
PHENIX Awareness, LockOut/TagOut	attected, RHIC Access, working at h	neignts	If union the manual table and	homoud votions are law sub-th-f-lls
Based on analysis above, the Walke ratings below:	Based on analysis above, the Walkdown Team determines the risk, complexity, and coordination ratings below:			I hazard ratings are low, only the following lowed, there is no need to use back of
ES&H Risk Level:	☐ Low ☐ Moderate	e High	WCC:	Date:
Complexity Level:	☐ Low ☐ Moderate	<u> </u>	Service Provider:	Date:
Work Coordination:	☐ Low ☐ Moderate		Authorization to start	Date:
		<u> </u>	(Departmental Sun/WCC/Des	

Work Plan (procedures, timing, equipment, and personnel availability need to be addressed): See Attached						
Special Working Conditions Required:						
No						
Operational Limits Imposed: No						
Post Work Testing Required: No						
Job Safety Analysis Required: Yes	☑ No		Walkdown Req	uired: 🗌 Yes 🔀 No		
Reviewed by: Primary Reviewer will de that the hazards and risks that could imp					mplexity	y. Primary Reviewer signature means
<u>Title</u>	Name (print)	<u>Signature</u>	·	Life #		<u>Date</u>
Primary Reviewer						
ES&H Professional						
Other						
Other						
Work Control Coordinator						
Service Provider						
	Review Done: in series	☐ team				
4. Job site personnel fill out this sec	tion.					
Note: Signature indicates personnel per	forming work have read and ur	derstand the hazards	and permit require	ements (including any attach	ments).	
Job Supervisor:			Contractor Supervisor:			
Workers:	Life#:		Workers : Life#:		Life#:	
Workers are encouraged to provide feedback on ES&H concerns or on ideas for improved job work flow. Use feedback form or space below.						
Workers are encouraged to provide feed	lback on ES&H concerns or on	ideas for improved job	o work flow. Use f	eedback form or space belov	W.	
5. Departmental Job Supervisor, Work Control Coordinator/Designee						
Conditions are appropriate to start work:	·	ork controls are in pla		ly for job.)		
Name:	Signature:		Life#:		Date:	
6. Departmental Job Supervisor, Wo	6. Departmental Job Supervisor, Work Requester/Designee determines if Post Job Review is required. Yes No					
Post Job Review (Fill in names of review	vers)					
Name:	Signature:		Life#: Date		Date:	
Name:	ame: Signature:		Life#: Date:			
7. Worker provides feedback.						
Worker Feedback (use attached sheets a) WCM/WCC: Is any feedback require						
b) Workers: Are there better methods or safer ways to perform this job in the future? Yes No						
8. Closeout: Work Control Coordinator (authorizing dept.) checks quality of completed permit and ensures the work site is left in an acceptable condition. (WCC can delegate clean up of work area to work supervisor)						
Name:	Signature:		Life#:		Date:	
Comments:						

Attachment toW/D	44	Iumo 7	2005
Attachment toW.P.	#	June 7,	4 005

Drift Chamber repair in the PHENIX Experimental Hall (bldg. 1008).

Problem

Certain FEM power supply modules on the west Drift Chamber have been failing to respond to ARCNET commands. It is likely that these are due to faulty LV or ARCNET cables. The intent is to trouble shoot these during the access period on June 8 or some other period between now and the end of Run 5 (June 25).

Access to the installed location of the modules is difficult, as they are located 10 to 20 feet above track level, tucked inside the arc formed by the RICH detector, with the Central Magnet in front of the west carriage. The procedure developed below was used successfully in the past to trouble shoot quite a few failed modules.

Work Plan

This work is to be done by fully trained and experienced personnel during an access period. Access to the power supply modules is by extension ladders set up between the central magnet (CM) outrigger and the RICH vessel on the west carriage. For the higher modules, two ladders will be secured side-by-side, tied together, to allow climbing by the CM pole piece. All detectors in the IR will contain flammable gas during this operation. There is no access to the DC, PC, or TEC gas windows from the location of the ladders and no danger of damage to the gas volume from their installation. The Drift Chamber high and low voltage will be turned off. The 12-ton building crane will be positioned such to place the eye of a sling directly above the work area, then locked out. A harness will be worn and clipped to the sling while the work is being performed. A watch must be present at all times when someone is up on the ladders. All work in the IR will be supervised by Sal Marino.

Work will involve trouble shooting of the modules and cables, and repair or replacement as appropriate.

- Ensure that power to the DC electronics is secured and that the CM power key is locked out of use.
- Erect and secure 1 (or 2 side by side if necessary) extension ladders between the top of the central magnet outrigger and the rich detector.
- Set up a tie off point just above the working position using the building crane and an adequately rated sling.
- The position of the tie off point is to be set for each working level and the crane must be locked out before the worker ascends the ladder.
- The worker is to use a body harness with a short clip-on lanyard and tie off before starting work.
- A watch must be present at all times when a person is on the ladders
- Remove or reinstall power supply modules as necessary.

